

Morris Leslie

PLANT SALES

Morris Leslie Final Inspection Form

ALL BOXES MUST BE COMPLETED WHERE APPLICABLE TO EACH MACHINE (WHERE NOT APPLICABLE NOTE N/A)

Year:	2021	Serial Number:	PS04013543	Machine Start Code:	0204#
Make:	KOBELCO	Model:	SK55SRX-6E		
Fleet Number:	SEL29546	Registration Number:	N/A		
Hour Clock Working:	Y	Machine Hours:	1060		
Tyre Size:	N/S/F%:	O/S/F%:	N/S/R%:	O/S/R%:	
Tracks (Steel/Rubber)		N/S % -		O/S % -	
Blade:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Track Width:			
Buckets:	4	Bucket Sizes:	DITCH, 2FT, 18 INCH, 12 INCH		
Roller Drum Width:		Roller -Water Sprinklers System			
Skip (Straight/Swivel/Hi-Tip):		Transmission (Hydrostatic/Gear):			
AdBlue:	N/A	4th Gear:	N/A		
Pallet Forks	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Fork Positioners	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Stabilisers:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Gross Weight(kg):	5140	Lift Capacity (kg):	N/A	Lift Height (m):	N/A
Engine (kw/hp) :	29.1	Turbo:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Air Conditioning:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Controls (Lever/Joystick):	JOYSTICK	Condition of Cab & Dash Decals	GOOD		
Hitch (Manual/Hydraulic):	HYDRAULIC	Reversing Camera	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
Body Work Condition (Any Damage):	GOOD DUE TO HOURS				
Glass (Any Damage):	N/A	Mirrors:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
Road Lights:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	WORKLIGHTS	GOOD		
Paintwork:	GOOD				
Auxiliary Pipe Work:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Double Acting:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Any other Comments OR Notes on the Condition:	N/A				
Amber Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Green Seat Belt Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
Date & Hours of Last Service:	N/A	Date Next Service Due:	N/A		
Last Service Sheet Attached:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Current Loler attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
THE LAST OR CURRENT RECORD OF THE SERVICE SHEET MUST BE SENT					
Service Records Supplied:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Red Key with Machine with picture:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
Manufacturers Decals with Machine:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
Depot:	810				
Inspected By:		Date:	11.08		